

## Ships detained in Hong Kong by PSC Section in February 2008

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8514435	GREAT PACIFIC	Panama	1985	4486	chemical tanker	Korean Register of Shipping	Panama Maritime Documentation Services; Korean Register of Shipping; Nippon Kaiji Kyokai	Ammships Pte Ltd	20/02/08	21/02/08	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: endorsement by flag States, the endorsement by flag for chief engineer and second engineer not available onboard, FIRE SAFETY MEASURES: fire-dampers, port and starboard fire dampers for engine room could not be closed, LIFESAVING APPLIANCES: maintenance and inspection, starboard lifeboat davit fwd and aft hooking o-ring found corroded and thinned out
2	9069451	HAI FA	Sierra Leone	1984	652	general cargo/multi-purpose ship	Panama Shipping Registrar Inc.	Panama Shipping Registrar Inc.	Dalian Mingfa Fishery Shipping Co Ltd	26/02/08	13/03/08	CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: endorsement by flag States, chief officer's COC not endorsed by flag state, SAFETY OF NAVIGATION: charts, Hong Kong charts not corrected to the latest ntm, echo-sounding device, echo sounding device not onboard, lights, shapes, sound-signals, vessel's whistle found malfunction, LIFESAVING APPLIANCES: rescue boats, rescue boat engine cannot start, MARPOL - ANNEX I: oil filtering equipment, engine room oil water separator found malfunction, FIRE SAFETY MEASURES: fire prevention, part of main engine exhaust pipe insulation material found missing, emergency fire pump, emergency fire pump not working properly

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.