

Ships detained in Hong Kong by PSC Section in February 2009

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7709370	HAI FU	Panama	1978	1792	Container	International Register of Shipping	China Corporation Register of Shipping; International Register of Shipping; Overseas Marine Certification Services (OMCS)	Ocean Grow International Shipmanagement Consultant Corp.	19/02/09		LIFESAVING APPLIANCES: lifeboats, lifeboat engine, lifebuoys, m.o.b. light and smoke damaged, inflatable liferafts, annual service overdue; CERTIFICATION AND WATCHKEEPING FOR SEAFARERS: endorsement by flag states, first engineer; MARPOL - ANNEX I: shipboard oil pollution emergency plan (SOPEP), not endorsed; SAFETY OF NAVIGATION: charts, not corrected, echo-sounding device, not working; RADIOCOMMUNICATIONS: MF radio installation, DSC test fail, maintenance/duplication of equipment, shore based maintenance agreement, radar transponder, not functioning; SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, waterborne overdue; FIRE SAFETY MEASURES: fire fighting equipment and appliances, fire main leaking

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.