

Ships detained in Hong Kong by PSC Section in June 2006

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	8201026	JUN LING	Panama	1981	3784	general cargo/multi-purpose ship	Isthmus Bureau of Shipping	Shanghai Guan Yu Ship Management Co., Ltd.	02/06/06	05/06/06	LOAD LINES: railing, cat walks, MARPOL RELATED OPERATIONAL DEFICIENCIES: garbage, LIFESAVING APPLIANCES: lifeboats, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room
2	7522643	CHIEF TAIN II	Panama	1977	19775	bulk carrier	China Corporation Register of Shipping	Jackson Shipping Safety Management Consultant Co., Ltd.	13/06/06	15/06/06	SAFETY OF NAVIGATION: nautical publications, LOAD LINES: ventilators, air pipes, casings, railing, cat walks, FIRE SAFETY MEASURES: readily availability of fire fighting equipment, LIFESAVING APPLIANCES: launching arrangements for survival craft, lifeboats
3	8123145	JAMOSAN	Korea, Democratic People's Republic	1981	1176	general cargo/multi-purpose ship	Korea Classification Society (former Josen CS)	Korea J.S. Shipping Co.	15/06/06	16/06/06	SAFETY OF NAVIGATION: voyage or passage plan, charts, STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, FIRE SAFETY MEASURES: fire fighting equipment and appliances/two breathing apparatus low pressure alarm not working
4	8631386	SHENG HUI	Panama	1987	1355	general cargo/multi-purpose ship	Panama Maritime Surveyors Bureau Inc	Fuzhou Hailing Shipping Co., Ltd.	19/06/06	21/06/06	SAFETY OF NAVIGATION: charts, nautical publications, navigation bridge visibility, RADIOCOMMUNICATIONS: reserve source of energy, LOAD LINES: covers (hatchway-, portable-, tarpaulins, etc.), WORKING SPACES (ILO 147): lighting, safe means of access, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, FIRE SAFETY MEASURES: emergency fire pump
5	7617565	YANG BING	Panama	1976	4003	general cargo/multi-purpose ship	China Corporation Register of Shipping	Hua Long (Thai) Co. Ltd.	20/06/06	21/06/06	SAFETY OF NAVIGATION: nautical publications, LOAD LINES: ventilators, air pipes, casings, doors, FOOD AND CATERING (ILO 147): ventilation, PROPULSION AND AUXILIARY MACHINERY: cleanliness of engine room, WORKING SPACES (ILO 147): safe means of access
6	9168403	UNICORN NO. 2	Panama	1997	5185	general cargo/multi-purpose ship	Nippon Kaiji Kyokai	Taiyo Sangyo Trading & Marine Service	21/06/06	22/06/06	SAFETY OF NAVIGATION: charts/navigational publication NP30, NP32 & ITU publications list IV, V, VII a not updated, nautical publications/IAMSAR manual not updated, distress messages: obligations and procedures/distress message received on 7 Jun 2006 from MMSI563181000 without log entry and proper response procedures, FIRE SAFETY MEASURES: fixed fire extinguishing installation/paint locker sprinkler not working properly, ISM RELATED DEFICIENCIES: resources and personnel/officers not conversant with the operation of fixed CO ₂ system

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.