

Ships detained in Hong Kong by PSC Section in May 2009

No	IMO Number	Ship Name	Flag	YOB	GRT	Ship Type	Class	Related ROs	Ship Company	Date of Detention	Date of Release	Nature of Deficiencies (responsible RO, if any)
1	7626841	SABLE CAPE	Saint Vincent and the Grenadines	1976	1714	Tugboat	American Bureau of Shipping	Det Norske Veritas; American Bureau of Shipping	Tschudi Ship Management AS	07/05/09	08/05/09	LIFESAVING APPLIANCES: inflatable liferafts, two davit launch liferafts provided on board without davit launch arrangement and without proper instruction; inflatable liferafts, two davit launch liferafts "hru" not properly fitted; SAFETY OF NAVIGATION: voyage or passage plan, voyage passage plan from Singapore to Hong Kong only for sea passage, plan for Hong Kong to Shanghai (next port) not correct with chart; SOLAS RELATED OPERATIONAL DEFICIENCIES: abandon ship drills, no clear record when the survival craft was lowered to water and maneuvering tested in 3 months; STABILITY, STRUCTURE AND RELATED EQUIPMENT: steering gear, emergency steering gear handle missing
2	8107529	STAR HUANGPU	Panama	1982	76290	Bulk carrier	Panama Maritime Documentation Services	Det Norske Veritas; Panama Maritime Documentation Services	Glory Wealthy Ship Management Co. Ltd.	08/05/09	22/05/09	MARPOL - ANNEX V : garbage management plan, large quantity garbage was placed on the after main deck; SAFETY OF NAVIGATION: nautical publications, latest notice to mariners was up to week 48/2008, voyage or passage plan, latest voyage plan was prepared up to 1-April-2009, voyage data recorder (VDR), the VDR was out of order; LIFESAVING APPLIANCES: lifeboats, starboard lifeboat forward hull/deck connection was detached and not watertight; FIRE SAFETY MEASURES: fire-dampers, e/r and funnel dampers operation gear seized, readily availability of fire fighting equipment, fire line at port accommodation forward holed; ISM RELATED DEFICIENCIES: maintenance of the ship and equipment, the safety management system is not properly implemented on board
3	7405687	ETOILE	Panama	1977	64785	Bulk carrier	Det Norske Veritas	Bureau Veritas; Det Norske Veritas	Good Faith Shipping Co SA	21/05/09	22/05/09	STABILITY, STRUCTURE AND RELATED EQUIPMENT: emergency lighting, batteries and switches, emergency generator not ready to start; MARPOL - ANNEX I: oil filtering equipment, oily water separator oil content meter not ready to test & operate

Note: The classification societies listed are not necessarily the entities carrying out the surveys relevant to the deficiencies that warranted detention and/or for issuing the certificates.